

# NEW LAGUN BUSHINGS

New Bushings are being implemented to include 'teeth', which will prevent the Arm from being assembled upside down.

Proper assembly of the parts is essential to ensure proper function.

\*Please ensure Tap is inserted flush into Bushing\*



**TMP (under tabletop)**



**ARM**

