





Replacing your power awning arm

Use these instructions to determine what awning arm is compatible with your RV. Below is where to find the part number on your awning and hardware. Note that the awning arm part number is the most important for finding the replacement. The awning tube number is useful to have and can assist in narrowing down the hardware number, if the hardware number is not available. Note that the identification tag location may vary based on the age and type of the awning.



Part Number Identification

8951001.400	8951 Power Patio Basement Hardware
8951002.400	8951 Power Patio Standard Hardware
8952001.400	8952 Power Patio Basement Hardware
8952001.410	8952 Power Patio Basement Hardware-Winnebago
8952002.400	8952 Power Patio Standard Hardware
8952002.410	8952 Power Patio Standard Hardware-Winnebago
8952003.400	8952 Power Patio Reduced Pitch Hardware
8952011.400	8952 Power Patio Basement Hardware Top Wire Exit
8952012.400	8952 Power Patio Standard Hardware Top Wire Exit
8952012.402	8952 Power Patio Standard Hardware
8952013.400	8952 Power Patio Reduced Pitch Hardware Top Wire Exit
8952021.400	8952 Power Patio Basement Hardware
8952102.400	8952 Power Patio Standard Hardware X-Projection Winnebago
8952102.410	8952 Power Patio Standard Hdwr, X-Proj, Winnebago
8952201.400	8952 Power Patio Basement Hardware w/Arm Bumpers
8952202.400	8952 Power Patio Standard Hardware w/Arm Bumpers
8952203.400	8952 Power Patio Reduced Pitch Hardware w/Bumpers
8952212.400	8952 Power Patio Standard Hardware w/Arm Bumpers
8952302.410	8952 Power Patio Std Hdwr,X-Proj, Winn, w/Bumpers
8956001.400(X)	8956 Power Channel Basement Hardware
8956002.400(X)	8956 Power Channel Standard Hardware
8956003.400(X)	8956 Power Channel Reduced Pitch Hardware
8956013.400(X)	8956 Power Channel Reduced Pitch Hardware
8957001.400(X)	8957 Power Channel Basement Hardware
8957002.400(X)	8957 Power Channel Standard Hardware
8957003.400(X)	8957 Power Channel Reduced Pitch Hardware
8957013.400(X)	8957 Power Channel Reduced Pitch Hardware
8957023.400(X)	8957 Power Channel Reduced Pitch Hardware
8962001.400(X)	8962 Power Patio 9200 Basement Hardware
8962001.410(X)	8962 Power Patio 9200 Basement Hardware - Winnebago
8962002.400(X)	8962 Power Patio 9200 Standard Hardware
8962002.410(X)	8962 Power Patio 9200 Std Hardware - Winnebago
8962003.400(X)	8962 Power Patio 9200 Reduced Pitch Hardware
8962011.400(X)	8962 Power Patio 9200 Basement Hardware Top Wire Exit
8962012.400(X)	8962 Power Patio 9200 Standard Hardware Top Wire Exit
8962013.400(X)	8962 Power Patio 9200 Reduced Pitch Hardware Top Wire Exit



Panther RV Products LLC
4060 S Grant St. #114
Washougal, WA 98671
Ph: 360-844-5398

Replacement Part Numbers

Model No.	Replacement Set	Left Hand	Right Hand
8951001.400	Out of Production	-	-
8951002.400	Out of Production	-	-
8952001.400	8952001.400	3312487.030	3312487.014
8952001.410	Contact Winnebago	-	-
8952002.400	8952002.400	3312487.022	3312487.006
8952002.410	Contact Winnebago	-	-
8952003.400	8952003.400	3312487.345	3312487.337
8952011.400	8952001.400*	3312487.030*	3312487.014*
8952012.400	8952002.400*	3312487.022*	3312487.006*
8952012.402	Out of Production	-	-
8952013.400	8952003.400*	3312487.345*	3312487.337*
8952021.400	Out of Production	-	-
8952102.400	Contact Winnebago	-	-
8952102.410	Contact Winnebago	-	-
8952201.400	8952001.400**	3312487.030**	3312487.014**
8952202.400	8952002.400**	3312487.022**	3312487.006**
8952203.400	8952003.400**	3312487.345**	3312487.337**
8952212.400	8952002.400***	3312487.022***	3312487.006***
8952302.410	Contact Winnebago	-	-
8956001.400(X)	Out of Production	-	-
8956002.400(X)	Out of Production	-	-
8956003.400(X)	Out of Production	-	-
8956013.400(X)	Out of Production	-	-
8957001.400(X)	Out of Production	-	-
8957002.400(X)	Out of Production	-	-
8957003.400(X)	Out of Production	-	-
8957013.400(X)	Out of Production	-	-
8957023.400(X)	Out of Production	-	-
8962001.400(X)	8952001.400	3312487.030	3312487.014
8962001.410(X)	Contact Winnebago	-	-
8962002.400(X)	8952002.400	3312487.022	3312487.006
8962002.410(X)	Contact Winnebago	-	-
8962003.400(X)	8952003.400	3312487.345	3312487.337
8962011.400(X)	8952001.400*	3312487.030*	3312487.014*
8962012.400(X)	8952002.400*	3312487.022*	3312487.006*
8962013.400(X)	8952003.400*	3312487.345*	3312487.337*

* The replacement is a bottom wire exit and will require you to move the wire to the correct location.

** The replacement does not include arm bumpers, you can re-use your current bumpers or purchase new bumpers (part# 3310777.000).

*** The replacement is a bottom wire exit and does not have arm bumpers. See the above comments.



Panther RV Products LLC
 4060 S Grant St. #114
 Washougal, WA 98671
 Ph: 360-844-5398

Left and Right Arm Identification

When choosing the left or right awning arm, look at the face of your awning from the outside.



Panther RV Products LLC
4060 S Grant St. #114
Washougal, WA 98671
Ph: 360-844-5398